WORK DETAILS

Name of work: Repair to Travel & Front Piping of Tata Hitachi Zx120-52473.

Sr. No.	Part Details				1.	3 To 10
	Part Number	Description	Qty		Rate	Amount
	way of supplying I	el & Front Piping of Tata Hitachi Zx120-52473 by ng Following Spare parts as per OEM a part number given below.				
A	Providing & fitting following spares as per OEM Specification					
1	4447483	Hose	1	No.		
2	4260127	Hose	1	No.		
3	4259322	Hose	1	No.	-	
В	LABOUR CHARGES					
- 1	Removing and refitting high pressure hose assembly			Job		
2	Fuel Tank opening ceaning, brazing & refitting		1	Job		
					GST 18%	
					Total Rs	

Deputy Engineer

Mechanical Subdivision, Latur