


**Name of Work : Repairs & Reconditioning to Arm jack (Stick Jack) Assly
of Tata Hitachi 120 H No. 52466**

Sr.No	Description of Job	Qty.
	Repairs & Reconditioning to Arm jack (Stick Jack) Assly of Tata Hitachi 120 H No. 52466	
A	Cost of Spare	
1	TC01376/40 - Seal Kit	1 No.
2	TC01373/9 - Pipe S/A	1 No.
B	Cost of Labour	
1	Removing Arm Jack Assembly from machine	1 Job
2	Dismantalling The Cylinder Assly, Cleaning, Replacing, Seal Service Kit	1 Job
3	Cylinder piston Rod Bend checking & removing	1 Job
4	Fitting Boom Cylinder Assly to Machine	1 Job


Deputy Engineer

Mechanical Sub division No. 3
Osmanabad