

WORK DETAILS

Name of work : Repair to Side branch & Travel Piping of Tata Hitachi Zx120-52473.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to Side branch & Travel Piping of Tata Hitachi Zx120-52473 by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4250063	Hose	1	No.		
2	4258284	Hose	2	No.		
3	4219356	Hose	2	No.		
B	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly		5	Job		
GST 18%						
Total Rs						



Deputy Engineer
Mechanical Subdivision, Latur