Name of work :Repairs to Hydraulic System by replacing Hose of Sany 140 Excavator
No.14381161

Sr. No.	Description	1	Qty	Unit	Rate	Amou
1	2		4	5	6	7
A	Repairs to Hydraulic System by replacing Hose of Sany 140 Excavator No.14381161 by removed old, leakage Hoses & providing and fitting new Hydraulic Hoses as per OEM specification gives					noving given belo
1	B230103006438	Rubber Hose	2	No		
2	B230103006439	Rubber Hose	1	No		
3	B230103006441	Rubber Hose	1	No	下线	S
4	B230103001830	Rubber Hose	2	No		
5	B230103007774	Rubber Hose	1	No		
В	Cost of Labour Charges					3/1
1	Removing & refitting high pressure hose assly		7	Jöb		
			,		Total:	
GST 9 %						
	No.				GST 9 %	
-	•			274	Grand total	

(B.V.Satpute)

Deputy Engineer

Mechanical Subdivision No. 02,

Dharashiv