

WORK DETAILS

Name of work : Repair to Travel & Front Piping of Tata Hitachi Zx120-52806.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to Travel & Front Piping of Tata Hitachi Zx120-52806 by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4447483	Hose	1	No.		
2	4260127	Hose	1	No.		
3	4259322	Hose	1	No.		
B	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly		3	Job		
GST 18%						
Total Rs						



Deputy Engineer
Mechanical Subdivision, Latur