

Name of work :Repairs to Arm Jack Assly hydraulic system and supply of spares to (L.H. side)
Sany 140 Excavator No.14381161

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	4	5	6	7
	Repairs to Arm Jack assly hydraulic system and supply of spares to LH side sany 140 Excavator No.14381161 as per OEM specification given below.				
A	Cost of Spares Charges				
1	60325952 - Arm Cylinder Kit	1	No		
2	60235894 - Right Glass	1	No		
3	3814141 - Cummins Rpm Sensor	1	No		
4	60213378 - Rubber Hose	2	No		
B	Cost of Labour Charges				
1	Removing & refitting high pressure hose assly (H/06)	2	Job		
2	Removing bucket/arm/boom jack assly,from machine and refitting after repairs (H/08)	1	Job		
3	Dismantling of jack assly,cleaning,inspection and replacement of seals with test & trial (H/09)	1	job		
4	Eye end rebuilding & making to STD size (H/10)	1	Job		
Total :					
GST 9 %					
GST 9 %					
Grand total					
Say Amount					

(B.V.Satpute)

Deputy Engineer

Mechanical Subdivision No. 02,
Dharashiv